

EWP Streambank Protection at East Brook Hillside Stabilization
Before and After Photos



Photo 1: Looking downstream from right streambank at upper portion of project area.



Photo 2: Looking upstream from right streambank at upper portion of project area after construction at right floodplain and hardened rock riffle structure.

EWP Streambank Protection at East Brook Hillside Stabilization
Before and After Photos



Photo 3: Looking downstream from right streambank at left eroding streambank.



Photo 4: Looking downstream after construction of bench along left streambank, stream channel to appropriate channel dimensions and right floodplain.

EWP Streambank Protection at East Brook Hillside Stabilization
Before and After Photos



Photo 5: Looking downstream from right streambank at lower portion of project area towards the Village of Walton.



Photo 6: Looking downstream from right streambank after construction of left bench with rip rap toe and floodplain on right streambank with erosion control material.