

EWP Streambank Protection at Gosper Road Project Site
Before and After Photos



Photo 1: Looking upstream from left streambank at culvert outfall and failing head walls.



Photo 2: Looking upstream from left streambank after construction of stacked rock headwalls and plunge pool.

EWP Streambank Protection at Gosper Road Project Site
Before and After Photos



Photo 3: Looking upstream from left streambank at culvert outfall and failing head walls.



Photo 4: Looking from left streambank at stacked rock headwall.

EWP Streambank Protection at Gosper Road Project Site
Before and After Photos



Photo 5: Looking downstream from Gosper Road after construction of plunge pool for culvert outlet protection.



Photo 6: Looking upstream after construction of stacked rock headwalls and plunge pool.