

Town of Walton Streambank Stabilization at Beers Brook Site A
Before and After Photos



Photo 1: Looking at right streambank erosion from Beers Brook Road.



Photo 2: Looking downstream after construction of rock rip rap along the toe of right streambank.

Town of Walton Streambank Stabilization at Beers Brook Site A
Before and After Photos



Photo 3: Looking upstream at right streambank erosion from Beers Brook Road.




Photo 4: Looking upstream after construction of rock rip rap along the toe of right streambank and a hardened riffle.

Town of Walton Streambank Stabilization at Beers Brook Site A
Before and After Photos



Photo 5: Looking downstream at culvert at lower end of project area.



Photo 6: Looking downstream after construction at culvert at lower end of project area with rock rip rap at the toe of the bank.