

Third Brook Sites 3, 4, 5, & 6
Bank Restoration and Stabilization Project
Before and After Photos



Photo 1: Looking at right streambank at lower portion of Site #3.



Photo 2: Looking downstream at the lower section of Site #3 after construction of rock wall and erosion control.

Third Brook Sites 3, 4, 5, & 6
Bank Restoration and Stabilization Project
Before and After Photos



Photo 3: Looking upstream at the middle section of Site #3.



Photo 4: Looking upstream at the lower section of Site #3 after construction of rock wall, hardened riffle and erosion control.

Third Brook Sites 3, 4, 5, & 6
Bank Restoration and Stabilization Project
Before and After Photos



Photo 5: Looking downstream at right eroding streambank at Site #4



Photo 6: Looking downstream at Site #4 after construction of stacked rock wall and erosion control.

Third Brook Sites 3, 4, 5, & 6
Bank Restoration and Stabilization Project
Before and After Photos



Photo 7: Looking downstream at right eroding streambank at Site #5.



Photo 8: Looking downstream at Site #5 after construction of stacked rock wall, rip rap, drainage ditch and erosion control.

Third Brook Sites 3, 4, 5, & 6
Bank Restoration and Stabilization Project
Before and After Photos



Photo 9: Looking downstream at right eroding streambank at Site #6.



Photo 10: Looking downstream at Site #6 after construction of rock weir structures and stream channel relocation..