

EWP Streambank Protection at Marvin Hollow Road  
Before and After Photos



**Photo 1:** Before construction, looking downstream from left streambank standing on private bridge.



**Photo 2:** After construction, looking downstream from left streambank standing on private bridge.



EWP Streambank Protection at Marvin Hollow Road  
Before and After Photos



**Photo 3:** Before construction, looking at right streambank standing on private bridge.



**Photo 4:** After construction, looking at right streambank standing on private bridge.



EWP Streambank Protection at Marvin Hollow Road  
Before and After Photos



**Photo 5:** Before construction, looking downstream from private bridge.



**Photo 6:** After construction, looking downstream from private bridge.



EWP Streambank Protection at Marvin Hollow Road  
Before and After Photos



**Photo 7:** Before construction, looking upstream from right streambank.



**Photo 8:** After construction, looking upstream from right streambank.



EWP Streambank Protection at Marvin Hollow Road  
Before and After Photos



**Photo 9:** Before construction, looking upstream from right streambank at lower portion of the project.



**Photo 10:** After construction, looking upstream from right streambank at lower portion of the project.